

Figure 1 consists of three schematic diagrams, (a), (b), and (c), illustrating the assembly and disassembly of a multi-stage sliding bearing system. The diagrams show a series of shafts (1a, 1b, 1c) and their corresponding bearing housings (2-1, 2-2, 2-3) mounted on a base (3-1, 3-2, 3-3). The bearing housings are connected by a common shaft (5). The diagrams show the bearing housings being moved relative to the shafts, with arrows indicating the direction of movement. The components are labeled with numbers 1a, 1b, 1c, 2-1, 2-2, 2-3, 3-1, 3-2, 3-3, 4a, and 4b.

FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6

